

1/10

PRIOR ART

WITHOUT PREFERENTIAL ADSORPTION

MORE PORE PLUGGING




FIG. 1A